# **Compressor Change**

ePB2109 | September 24, 2021



# See table There comp As Current Inventory numb is depleted Pricing Info: Available Now Warranty: No change

IMPORTANT DATES First Production:

### **RATINGS:**

AHRI ratings available at AHRIDirectory.org

### **Reason for Update:**

There's an increased demand for compressors and to alleviate the capacity constraint, new compressors will be used in the models listed below which will change the current model numbers to a new model number. Using these new compressors will improve lead times and increase product availability.

### **Important Notes:**

• The models listed below will remain as scroll compressors. We are only changing supplier for these units to increase product availability

• There is no change in AHRI Ratings between the new and old models. AHRI ratings stop at the 9th model digit which is unchanged between the new and old models.

• Replacement parts for the prior model are still active and valid in the system. Note the changed replacement part in the table

Pricing between the new and old model numbers are the same.

• Please note the move to lower breaker/ fuse from Wire Harness and existing Compressor Model Number Change. The bulletin is just highlighting the move from Wire Harness to Lower Breaker / Fuse and the existing and new compressor model numbers.

## Model Change/ Updates:

New/Prior	Current Production Model # (From)	New/Prior Model # (To)	Current Breaker (From)	New Breaker (To)	New Compressor Model	Production Start
New	A4AC3023A1000 <u>B</u> A	A4AC3023A1000 <mark>C</mark> A	30	20	LBA020	11/1/2021
New	A4AC3024A1000 <u>B</u> A	A4AC3024A1000 <mark>C</mark> A	30	20	LBA020	11/1/2021
New	A4AC4023A1000 <u>B</u> A	A4AC4023A1000 <mark>C</mark> A	30	20	LBA020	11/1/2021
New	A4AC4024A1000 <mark>B</mark> A	A4AC4024A1000 <mark>C</mark> A	30	20	LBA020	11/1/2021