

PRODUCT BULLETIN

eAPB1822

June 19, 2018

IMPORTANT DATES

First Production June 4, 2018

First Ship New models will ship when current inventory is depleted

Sales Literature Available Now

Technical Literature Available Now

Pricing Info No change

WARRANTY INFO

Registered Limited Warranty 12 Years Compressor, 10yr Coil and Functional Parts

Non-Registered Limited Warranty 5 Years Compressor, Coil and Functional Parts

RATINGS INFO

No change

AHRI ratings available at www.ahridirectory.org

NEW Gold 17 Heat Pump

American Standard will be making a change in the control circuit wiring to resolve a field reported issue of the EEV remaining powered when the Low Pressure Switch



opens, which causes the system to pump down and lockout when low on refrigerant charge. The Low Pressure switch will now be wired in series with the high pressure switch and the EEV so that power will be removed from the EEV when either pressure control opens to remove power from the EEV and prevent a pump down and possible lockout of the system. While this has not been a cause of frequent customer complaints, the change will improve customer satisfaction with our systems until the system can be serviced.

This control wiring change will not result in a change to price, product performance or system AHRI ratings.

The 14th digit of the model number is being changed from **'C'' to 'D''** to reflect this new control wiring change.

Note: The current models will ship until the inventory of current models is depleted.

Current Model	New Model
4A6H7024A1000 C	4A6H7024A1000 D
4A6H7036B1000 C	4A6H7036B1000D
4A6H7048A1000 C	4A6H7048A1000D
4A6H7060A1000 C	4A6H7060A1000D