

# Launching Awair® Element™



eAPB2121 | October 4, 2021

## IMPORTANT DATES

### Homeowner

#### Promotion Period:

Oct. 25–Nov. 22, 2021

#### Promo code:

ASAWAIR2021

American Standard Heating & Air Conditioning® has collaborated with Awair® to offer an integration with their home air quality device, the Element. The Element is a smart, all-in-one environmental sensor that homeowners can use to monitor their temperature, humidity, CO2, chemicals and PM2.5 levels (any fine dust or particulate matter that is 2.5 microns in width or smaller).

### Integration with American Standard Home

Homeowners have to purchase this device from Awair at [getawair.com](http://getawair.com) and then can integrate it with the American Standard Home app. They can view their Awair Score right from the app and opt in to the pre-programmed automation from American Standard Home. This automation uses the Awair Score to determine when the HVAC fan should run.

### Integration with American Standard Diagnostics

When homeowners opt into American Standard Diagnostics, Diagnostic Dealers will be able to:

1. See run time history and Awair data to help them pinpoint possible indoor air quality issues.
2. View the homeowner's 30 day history of Awair scores alongside the HVAC values to gain a clearer picture of what may be happening when scores are low.

**NOTE:** This badge will be shown when a homeowner integrates an Awair device using the American Standard Home app.

The badge will be shown for the thermostat(s) to which the homeowner has chosen to link their Awair device.

SYSTEM STATUS		Last updated: Mon, Oct 26, 2020 9:33AM					
Settings	Status	Outdoor Unit	Indoor Unit				
Firmware	5.9.2	Sys Mode	HEAT	Outdoor Temp	9.0°	Actual Airflow	--
Fan Mode	CIRCULATE	Indoor Status	HTG STG 1	Liquid Pressure	--	Static Pressure	--
Htg RH Setpoint	35%	Outdoor Status	IDLE	Suction Pressure	--	Evap/Liquid Temp	--
Clg RH Setpoint	50%	Fan Status	ON	OD Subcool	--	Gas Temp	--
		Airflow%	0%	OD Superheat	--		
		Emergency Heat	DISABLED				
		Sys Load Value	100				
		Humidifier	NOT INSTALLED				
		Dehumidifier	NOT INSTALLED				
		Ventilation	NOT INSTALLED				