

ePB2106 | August 13, 2021

IMPORTANT DATES

First Production:

August 23, 2021

First Ship:

As Current Inventory is depleted

Starting September, 6 2021 and going forward 13, 14, and 16 SEER 2.5 Ton Air Conditioner models will be produced with a Rotary compressor. The reason for this change is multi-fold, however, the primary short-term objective is to improve product availability during recent events impacting scroll compressor availability across the industry. We will work to update existing orders of the current model to the new model at the same price. This change will impact the following current models:

Current Model	New Model
A4AC3030A1000BA	A4AC3030A1000CA
A4AC4030A1000BA	A4AC4030A1000CA
A4AC6030A1000AA	A4AC6030A1000BA

Pricing Info:

Available Now

Warranty:

5 year limited parts

10 year registered

AHRI Ratings will not be impacted with this implementation of Rotary compressors on the 2.5T AC Models.

All models are subject to current lead times.

RATINGS:

AHRI ratings available at AHRIDirectory.org

We are very excited to share these changes and we invite you to review some exciting and unique features of our Rotary compressors on the attached product information sheet that is also available on the www.ameristarhvac.com website.

[CLICK HERE](#) for the "Why Rotary Compressors?" Product Information Sheet